Survey No. T-863

## Maryland Historical Trust State Historic Sites Inventory Form

DOE \_\_yes \_\_no

Magi No.

1. Nam	e (indicate pr	eferred name)		
historic				
and/or common	Joseph Jacksor	House		
2. Loca		110036		
street & number	Coopertown Roa	d		not for publication
city, town	Tilghman	vicinity of	congressional district	Fifth
state	MD	county	Talbot	
3. Clas	sification			
Category  district _X building(s) structure site object	Ownership public private both Public Acquisition in process being considered not_applicable	Status  X occupied  unoccupied  work in progress  Accessible  yes: restricted  yes: unrestricted  no	Present Use agriculture commercial educational entertainment government industrial military	museum park private residence religious scientific transportation other:
4. Own	er of Prope	rty (give names ar	nd mailing addresse	s of <u>all</u> owners)
name W:	illiam and Jane	Bissell		
street & number	7515 Lihirond	elle Club Road	telephone no	o.:
city, town	Baltimore	state	and zip code Md	21204
	ation of Leg	al Description	on	-
courthouse, regis	stry of deeds, etc. Talb	ot County Clerk	of Court	liber <sup>445</sup>
street & number	Talbot County	Courthouse		folio316
city, town	Easton		state	MD
6. Repi	resentation	in Existing	Historical Surv	eys
title				
date			federal stat	e county loca
pository for su	rvey records			
city, town			state	

## 7. Description

Survey No. T-863

Con	dition
	excellent
	good
_X_	fair

\_\_\_ deteriorated
\_\_\_ ruins
\_\_ unexposed

Check one unaltered X altered

Check one

X original site

moved date of move

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

The Joseph Jackson house is located on the west side of Route 33 and on the north side of Coopertown Road in the village of Tilghman on Tilghman Island, Talbot County, MD. The house faces south, with the principal gable oriented on an east/west axis.

Built in the late 1800s, the exterior of this two-story, frame house is clad in yellow cedar shake shingles. The roof is covered with asphalt shingles and the house is supported by a very low brick pier foundation.

The south (main) facade has a central door with a colonial revival door surround. The door is flanked by one six-over-six sash window with wide surrounds on either side. There are two six-over-six sash windows with wide surrounds on the second floor. A one-story, shed roof addition extends from the western end of the building. The south facade of this addition has a colonial revival bay window.

The west elevation of the primary structure's gable end has a blind second story with an interior brick chimney stack and cornice returns. A first floor shed addition extends to the rear of the house. This addition is lit by three irregularly spaced six-over-six sash windows.

The north (rear) elevation has one six-over-six sash window and one eight-over-eight sash window on the second floor. The first floor shed addition has one door and a pair of six-over-six sash windows.

The east elevation has one six-over-six sash window on the first floor of the primary wing and one on the northern shed addition. This gable end has cornice returns and the second floor is lit by one six-over-six sash window.

At one time the house was enclosed by an alternating iron and wood post fence. A wide plank outbuilding, now greatly overgrown, sits in the backyard. The interior was not seen.

Period — prehistoric — 1400–1499 — 1500–1599 — 1600–1699 — 1700–1799 — X 1800–1899 — 1900–	archeology-historic	community planning conservation economics education engineering exploration/settlement industry	landscape architecture law literature military music philosophy politics/government	religion science sculpture social/ humanitarian theater transportation
0		invention		other (specify
Specific dates		Builder/Architect		
check: Appl:	icable Criteria:A	B <u>X</u> CD		
App1:	icable Exception:A	BCDE	FG	
Leve	l of Significance:	national _state <u>X</u>	local	
Prepare both support.	a summary paragraph o	f significance and a	general statement of	history and

Survey No

8. Significance

The Joseph Jackson house is a simple two-story, single pile structure which represents the earliest type of dwelling built for watermen and their families. Typical of these dwellings is the minimal use of decorative trim. In the village of Tilghman, most of these surviving buildings appear to be located on the west side of Route 33.

Joseph Jackson is remembered as a long time resident of this Coopertown Road house.

## 9. Major Bibliographical References

Survey No. T-863

10.	eographical [	Data		
Quadrangle	nominated property name nces do NOT complete U		Quadra	ngle scale
<b>^</b> [	Easting Northing	B Zone	Easting	Northing
C		P		
Verbal bou	ındary description and justi	fication		
List all sta	ites and counties for proper	ties overlanning etate or	county houndarie	
	i <b>tes and counties for proper</b>	ties overlapping state or	county boundarie	es code
<b>List all sta</b> state state	СС	_	county boundarie	
state state	СС	ode county	county boundarie	code
state 11. F	Co	ode county  By		code
state state 11. F	orm Prepared	ode county  By  architectural his		code
state state 11. F	Corm Prepared Elizabeth Hughes, Talbot County Plan	ode county  Dode county  By  architectural his  ning Office	torian	code

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.


The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to: Maryland Historical Trust

Shaw House 21 State Circle

Annapolis, Maryland 21401

(301) 269-2438





JOSEPH JACKSON HOUSE

E. HUGHES, PHOTO.

T-863



T-863

Joseph Jackson Youse